



PAKISTAN NOTICES TO MARINERS

WEEKLY EDITION 25

Notice: 74 – 76/23

24 JUN 2023

Copies of these Notices can be obtained gratis from Mercantile Marine Department and PN Chart Depot / NAVAREA IX Headquarters, 11 Liaquat Barracks Karachi. The same can be downloaded from web: hydrography.paknavy.gov.pk.

CONTENTS

- I NOTICES TO MARINERS
- II REPRINTS OF RADIO NAVIGATIONAL WARNINGS
- III CORRECTIONS TO SAILING DIRECTIONS
- IV MARINE INFORMATION

Mariners are requested to inform the Hydrographic Department, Naval Headquarters, 11 Liaquat Barracks, Karachi, Pakistan, immediately on the discovery of new dangers, or suspected dangers to navigation and of changes or defects in aids to navigation noticed in NAVAREA IX and of shortcomings in PAK charts or publications.

Tel : + 92-21-48506151
+ 92-21-48506152
Fax : + 92-21-99201623
+ 92-21-35867737

E-mail : hydropk@paknavy.gov.pk
hydrpk@gmail.com

Web : hydrography.paknavy.gov.pk.

MUHAMMAD WASIM
Captain Pakistan Navy
Hydrographer

National Hydrographic Office, Naval Headquarters, 11 Liaquat Barracks, Karachi 75530, PAKISTAN

PART – I
NOTICES TO MARINERS

74/23 OMAN - Depth.**BA Chart 3762** [*previous update 431/23*] WGS84 DATUMDelete depth, 15₄, and associated 20m contour 19° 44′·71N., 57° 51′·77E.**BA Chart 3763** [*previous update 431/23*] WGS84 DATUMDelete depth, 15₄, and associated 20m contour 19° 44′·72N., 57° 51′·77E.

Source: Admiralty Notice to Mariners No. 2089/2023

75*/23 SAUDI ARABIA - Red Sea Coast - Alongside depths. Depths.**BA Chart 328 (INT 7147)** [*previous update 4152/22*] WGS84 DATUM

Insert	depth, 16 ₄	23° 58′·01N., 38° 11′·91E.
	depth, 17 ₅	(a) 23° 57′·76N., 38° 12′·20E.
Delete	depth, 18, close NW of:	(a) above
Insert	depth, 26	(b) 23° 56′·91N., 38° 10′·77E.
Delete	depth, 27, close SE of:	(b) above
Insert	depth, 21	(c) 23° 56′·95N., 38° 12′·66E.
Delete	depth, 27 ₅ , close E of:	(c) above
Insert	alongside depth, •(15 ₁)	(d) 23° 57′·09N., 38° 13′·15E.
Delete	depth, 17, close W of:	(d) above
Insert	alongside depth, •(15 ₂)	(e) 23° 57′·05N., 38° 13′·29E.
Delete	depth, 17 ₉ , close SW of:	(e) above
Insert	depth, 19, enclosed by 20m contour	23° 56′·77N., 38° 13′·11E.
	depth, 17 ₇ , and extend 20m contour E to enclose	23° 56′·60N., 38° 13′·47E.
	alongside depth, •(13 ₆)	(f) 23° 57′·08N., 38° 13′·87E.
Delete	depth, 14 ₃ , close S of:	(f) above
Insert	alongside depth, •(19 ₄)	(g) 23° 55′·80N., 38° 15′·22E.
Delete	depth, 24, close SW of:	(g) above
Replace	depth, 28, with depth, 26 ₅	23° 56′·64N., 38° 13′·22E.
	depth, 28, with depth, 22 ₅	23° 54′·67N., 38° 17′·39E.

Source: Admiralty Notice to Mariners No. 1955/2023

76/23 PAKISTAN - Buoy.**BA Chart 40 (INT 7315)** [*previous update 2142/22*] WGS84 DATUM

Amend designation of buoy to, TS-2 24° 47′·726N., 66° 59′·465E.

Source: Admiralty Notice to Mariners No. 2090/2023

PART – II
RADIO NAVIGATIONAL WARNINGS

252/23. PAKISTAN. Karachi approaches. Charts PAK 5 (INT 7314), 30 (INT 7315), BA 40 and 58. Channel buoy S-7 in position 24-45.49N 066-58.13E reported missing. Mariners cautioned.**253/23. SELF CANCELLING.** Operation completed. Cancel Navarea IX warning 175 of 2023.**254/23. CENTRAL GULF.** South Bahrain. Charts BA 2886. New special mark buoy established in position 25-47.40N 050-37.10E with characteristics Fl.Y.4s. Mariners cautioned.**255/23. SELF CANCELLING.** Buoy replaced. Cancel Navarea IX warning 325 of 2022.

256/23. NORTHERN GULF. Kuwait. Charts BA 1223, 3773 and KU Charts 1,4 and 9. New lateral mark buoys established in Al-Zour port as under:

KOC BH1	28-42.827N	048-24.281E	Fl.G.3s
KOC BH2	28-42.647N	048-24.328E	Fl.R.3s
KOC BH3	28-42.862N	048-24.054E	Fl.G.3s
KOC BH4	28-42.715N	048-24.197E	Fl.R.3s
KOC BH5	28-42.906N	048-23.817E	Fl.G.3s
KOC BH6	28-42.776N	048-23.998E	Fl.R.3s
KOC BH8	28-42.838N	048-23.783E	Fl.R.3s

Mariners cautioned.

257/23. SELF CANCELLING. Operation completed. Cancel Navarea IX warning 235 of 2023.

258/23 SELF CANCELLING Navigational Warnings Inforce:

2021 series: 109, 224, 397, 399, 445, 448, 490 and 491.

2022 series: 027, 039, 067, 095, 102, 112, 142, 144, 180, 185, 198, 211, 220, 227, 294, 295, 311, 328, 331, 358, 443, 477, 480, 483, 489, 497, 501, 505, 506, 507 and 513.

2023 series: 025, 028, 034, 058, 065, 067, 068, 070, 071, 072, 094, 096, 102, 103, 110, 111, 112, 116, 120, 124, 131, 135, 138, 142, 157, 159, 167, 177, 190, 199, 201, 214, 217, 221, 224, 226, 237, 239, 243, 245, 248, 249, 252, 254 and 256.

COASTAL WARNING

062/23. PAKISTAN. Karachi approaches. Charts PAK 5 (INT 7314), 30 (INT 7315), BA 40 and 58. Channel buoy S-7 in position 24-45.49N 066-58.13E reported missing. Mariners cautioned.

063/23 SELF CANCELLING Navigational Warnings Inforce:

2022 series: 024, 027, 060, 063, 081 and 082

2023 series: 027, 050, 056 and 062

WPGs Inforced 2023: 24

WPGs Cancelled 2023: Nil

PART – III

CORRECTIONS TO SAILING DIRECTIONS

Nil

PART – IV

MARINE INFORMATION

Nil

NP77, Vol D Edition 2023. Weekly Edition No. 25, Dated 22 June 2023.
 Last Updates: Weekly Edition No. 24, dated 15 June 2023.

D7681	Bandar e Shiu	27 04-77 N 53 08-65 E	Fl(2)W 12s *	18	12 Red and white metal tower	..
D7681-5	Bandar-e Moqām (IR)	26 58-27 N 53 28-27 E	Fl(2)W 12s *	20	12
D7715-3	Bandar-e Jask. E Breakwater. Head	25 39-56 N 57 49-14 E	Fl R 5s *	..	5 Red □ on red beacon tower	.. * * *
D7716	Bandar-e Jask. E Breakwater. Head	25 39-49 N 57 49-16 E	Fl G 5s *	..	5 Green △ on green beacon tower	.. * * *