



PAKISTAN NOTICES TO MARINERS

WEEKLY EDITION 01

Notice: 01 – 06(T)/21

09 JAN 2021

Copies of these Notices can be obtained gratis from Mercantile Marine Department and PN Chart Depot / NAVAREA IX Headquarters, 11 Liaquat Barracks Karachi. The same can be downloaded from web: www.paknavy.gov.pk/hydro.

CONTENTS

- I NOTICES TO MARINERS
- II REPRINTS OF RADIO NAVIGATIONAL WARNINGS
- III CORRECTIONS TO SAILING DIRECTIONS
- IV MARINE INFORMATION

Mariners are requested to inform the Hydrographic Department, Naval Headquarters, 11 Liaquat Barracks, Karachi, Pakistan, immediately on the discovery of new dangers, or suspected dangers to navigation and of changes or defects in aids to navigation noticed in NAVAREA IX and of shortcomings in PAK charts or publications.

Tel : + 92-21-48506151
+ 92-21-48506152
Fax : + 92-21-99201623
+ 92-21-35867737

E-mail : hydropk@paknavy.gov.pk
hydropk@gmail.com

Web : www.paknavy.gov.pk/hydro.

MUHAMMAD KHALID
Commodore
Hydrographer

Hydrographic Department, Naval Headquarters, 11 Liaquat Barracks, Karachi 75530, PAKISTAN

PART – I
NOTICES TO MARINERS

01/21 KUWAIT - Wrecks.

Note: Former Notice 4325(T)/20 (PAK Notice 129(T)/20) is cancelled.


BA Chart 1265 (INT 7291) [*previous update 4724/20*] WGS84 DATUM

Insert		(a) 29° 21'·72N., 48° 53'·04E.
Delete	 , close NE of:	(a) above
Replace	 with  ED	29° 23'·63N., 48° 52'·46E.

BA Chart 2847 (INT 7018) [*previous update 6168/20*] WGS84 DATUM

Replace	 with  ED	29° 23'·6N., 48° 52'·5E.
	 with 	29° 21'·7N., 48° 53'·0E.

BA Chart 2882 (INT 7264) [*previous update 5518/20*] WGS84 DATUM

Replace	 with  ED	29° 23'·6N., 48° 52'·5E.
	 with 	29° 21'·7N., 48° 53'·0E.

BA Chart 2884 (INT 7278) [*previous update 5518/20*] WGS84 DATUM

Replace	 with  ED	29° 23'·6N., 48° 52'·5E.
	 with 	29° 21'·7N., 48° 53'·0E.

BA Chart 3773 [*previous update 5630/20*] WGS84 DATUM

Replace	 with  ED	29° 23'·63N., 48° 52'·46E.
	 with 	29° 21'·72N., 48° 53'·04E.

Source: Admiralty Notice to Mariners No. 44/2021.

02/21 QATAR - Platform.

BA Chart 3950 (INT 7244) [*previous update 6168/20*] WGS84 DATUM

Insert	 IS-U08C	25° 29'·27N., 52° 22'·56E.
--------	---	----------------------------

Source: Admiralty Notice to Mariners No. 49/2021.

03*/21 KUWAIT - Automatic Identification Systems. Note.

BA Chart 1223 [*previous update 5630/20*] WGS84 DATUM

Insert	the accompanying note, AUTOMATIC IDENTIFICATION SYSTEMS	within title panel
--------	---	--------------------

BA Chart 2882 (INT 7264) [*previous update 44/21*] WGS84 DATUM

Insert	Automatic Identification System, AIS, at light-buoy	28° 43'·9N., 48° 27'·0E.
		28° 44'·3N., 48° 26'·7E.

BA Chart 2884 (INT 7278) [*previous update 44/21*] WGS84 DATUM

Insert	Automatic Identification System, AIS, at light-buoy	28° 43'·9N., 48° 27'·0E.
		28° 44'·3N., 48° 26'·8E.

Source: Admiralty Notice to Mariners No. 88*/2021.

04(T)/21 Pakistan - Wreck.

Source: PMSA letter, Navarea IX warning 290 and 422 of 20.

Note: Former Pakistan Notice 124(T)/20 is cancelled

1. Wrecks (small fishing boats approx 15 meters long) reported in following positions:

- | | |
|----------------|----------------|
| (a) SSS-09 | 24-31N 066-57E |
| (b) Al Rizwana | 24-49N 066-36E |
| (c) Al-Ayub | 24-42N 066-41E |

2. Mariners are advised to navigate with caution in the area.

3. Chart will be updated when full details of wrecks are known.

Charts affected PAK 5 (INT 7314), 22, 30 (INT 7315), 57 (INT 751), 58 (INT 7019), BA 39 and 58.

05(P)/21 EGYPT - Suez Canal - Buoyage. Anchor berth.

1. The following lateral light-buoys have been established:

<i>Characteristic</i>	<i>Position</i>
<i>F.R</i>	31° 10'·29N., 32° 20'·60E.
<i>F.G</i>	31° 10'·34N., 32° 20'·45E.
<i>F.R</i>	31° 09'·60N., 32° 20'·41E.
<i>F.G</i>	31° 09'·64N., 32° 20'·26E.

2. Yellow light-buoys, *Q*, have been established in the following positions:

- 31° 09'·48N., 32° 20'·50E.
- 31° 09'·37N., 32° 20'·58E.
- 31° 09'·19N., 32° 20'·62E.
- 31° 09'·05N., 32° 20'·48E.
- 31° 09'·11N., 32° 20'·22E.
- 31° 09'·28N., 32° 20'·16E.

3. The following anchor berth, and associated mooring-buoy, have been removed:

<i>Designation</i>	<i>Position</i>
8A	31° 15'·842N., 32° 19'·403E.

4. These and other changes will be included in the next New Edition of Chart 240. (WGS84 DATUM)

BA Chart affected - 240 (INT 3549)

Source: Admiralty Notice to Mariners No. 60(P)/2021.

06(T)/21 SAUDI ARABIA - East Coast - Wreck. Buoyage.

1. A wreck has been reported in position 26° 31'·18N., 50° 12'·47E.
2. Two special light-buoys, *Q.Y*, have been deployed to mark the wreck, in positions 26° 31'·22N., 50° 12'·44E. and 26° 31'·14N., 50° 12'·50E.
3. Mariners are advised to navigate with caution in the area. (WGS84 DATUM)

BA Charts affected - 3777 (INT 7266) - 3812 (INT 7268)

Source: Admiralty Notice to Mariners No. 121(T)/2021.

PART - II
RADIO NAVIGATIONAL WARNINGS

002/21. NORTHERN GULF. Iraq. Khawr az Zubayr. Charts BA 1228 and 2884. Navcent reported limpet mine was placed on the hull of a vessel while in the vicinity of the Khawr Az Zubayr anchorage on 31 December 2020. Vessel recently visited the anchorage are advised to conduct frequent visual checks of their hull above and where possible, below the water line. Vessel crew remain vigilant and may report any suspicious small boat activity or unidentifiable floating objects to 'ukmcc-mso@mod.gov.uk and cusnc.ncags_bw@me.navy.mil'

003/21. OMAN. Gulf of Masirah. Charts BA 3785 and 4705. Dhow ship 'Mukrani' reported partly sunk in position 18-40.70N, 057-55.90E in vicinity of Oman approximately (19NM) southeast of Ra's Al Madraka. Mariners are requested to navigate with extreme cautioned and keep sharp look out.

004/21. YEMEN. Gulf of Aden. Charts BA 2964, 2970 and 4705. Reported dhow ship 'Al Kamen 1' hull colour white & brown loss communication while underway from Ash Shhir port to Suqutra Island with 5 crew members onboard. Mariners operating in the area are requested to keep sharp lookout and render assistance.

005/21. SOUTHERN GULF. U A E. Charts BA 2443, 2837, 2858, 2889 and 3178. Seismic survey is being conducted in area bounded by:

Crew 209 Area:
24-22.92N 051-58.31E
24-22.92N 052-10.88E
24-17.21N 052-10.88E
24-17.21N 051-58.31E

Crew 252 Area:
Node Spread Area
25-28.98N 053-40.67E
25-28.75N 053-52.67E
25-23.77N 053-52.56E
25-24.00N 053-40.56E

Shooting Area:
25-32.15N 053-44.35E

25-32.08N 053-48.21E
 25-20.60N 053-47.96E
 25-20.68N 053-44.09E

Mariners are advised to navigate with caution and to maintain a listening watch on channels 16/72 and 76. Cancel this message on 102359 UTC Jan 2021.

- 006/21. ARABIAN SEA.** Pakistan. Charts PAK 33, PAK 57 (INT 751), PAK 58 (INT 7019), BA 38 and 707. Naval units will carry out firing practice with live ammunition between 0400 to 1200 UTC from 08 to 13 Jan 21 in area bounded by:

24-56.00N 066-15.00E
 23-00.00N 066-15.00E
 23-00.00N 062-25.00E
 24-56.00N 062-25.00E
 25-20.00N 064-00.00E
 25-20.00N 065-15.00E

Ships and craft are to keep well clear of assigned danger area on above specified schedule. Cancel this message on 131300 UTC Jan 21.

- 007/21. SELF CANCELLING.** Cancel Navarea IX warning 426 of 2020

- 008/21. CENTRAL GULF.** Qatar. Charts BA 2523, 2837, 2858, 2886 and 3950. 24 hours ROV campaign will be conducted by vessel 'DSV Halul 49' from 01 Jan 21 to 01 Mar 21 for several platforms in the area bounded by following positions:

- a. 26-43.55N 051-50.86E
- b. 26-43.55N 052-04.09E
- c. 26-26.83N 052-04.09E
- d. 26-26.83N 051-50.86E

Mariners are requested to navigate with caution and give wide berth. Cancel Navarea IX warning 233 and 349 of 2020

- 009/21. CENTRAL GULF.** Bahrain. Charts BA 3736, 3738 and 3790. Diving operation for buoys inspections will be conducting on the following stations in Bahrain Outer and Mina Salman channels from 070300 to 071400 UTC Jan 21.

No.17 26-12.44N 050-47.03E
 Sitrah inward 26-21.15N 050-49.72E
 No.5 26-11.36N 050-38.00E

Mariners are requested to navigate with caution and give wide birth.

- 010/21. SELF CANCELLING.** Cancel Navarea IX warning 435 of 2020.

- 011/21. ARABIAN SEA.** Pakistan. Charts PAK 33, 57 (INT 751), 58 (INT 7019), BA 38 and 707. Naval ships will carry out depth charge live firing practice between 0400 to 1700 UTC on 08 and 11 to 13 Jan 2021 in area bounded by:

24-16.18N 066-20.50E
 24-22.00N 066-27.00E
 24-16.30N 066-33.00E
 24-10.30N 066-27.00E

Ships and craft are to keep well clear of assigned danger area on above specified schedule. Cancel this message on 131800 UTC Jan 2021. Cancel Navarea IX warning 467 of 2020.

- 012/21. SELF CANCELLING.** Cancel Navarea IX warning 406/19, 019/20 and 047/20. Warning printed in Pakistan Notice to Mariners Weekly Edition 53 (Part-IV) of 2020.

- 013/21. SELF CANCELLING.** Navarea IX Warnings inforce:

2019 series: 096, 126, 146, 167, 221, 335, 381 and 393.
 2020 series: 004, 018, 035, 078, 150, 178, 184, 187, 209, 215, 222, 225, 238, 266, 270, 277, 331, 336, 337, 340, 350, 379, 384, 387, 394, 406, 408, 409, 416, 422, 424, 427, 429, 431, 449, 451, 453, 463 and 466.
 2021 series: 002, 003, 004, 005, 006, 008 and 011.

COASTAL WARNING

- 002/21. ARABIAN SEA.** Pakistan. Charts PAK 33, PAK 57 (INT 751), PAK 58 (INT 7019), BA 38 and 707. Naval units will carry out firing practice with live ammunition between 0400 to 1200 UTC from 08 to 13 Jan 21 in area bounded by:

24-56.00N 066-15.00E
 23-00.00N 066-15.00E
 23-00.00N 062-25.00E
 24-56.00N 062-25.00E
 25-20.00N 064-00.00E
 25-20.00N 065-15.00E

Ships and craft are to keep well clear of assigned danger area on above specified schedule. Cancel this message on 131300 UTC Jan 21.

- 003/21. ARABIAN SEA.** Pakistan. Charts PAK 33, 57 (INT 751), 58 (INT 7019), BA 38 and 707. Naval ships will carry out depth charge live firing practice between 0400 to 1700 UTC on 08 and 11 to 13 Jan 2021 in area bounded by:

24-16.18N 066-20.50E
24-22.00N 066-27.00E
24-16.30N 066-33.00E
24-10.30N 066-27.00E

Ships and craft are to keep well clear of assigned danger area on above specified schedule. Cancel this message on 131800 UTC Jan 2021. Cancel coastal warning 154 of 2020.

004/21. SELF CANCELLING. Navigational Warnings Inforce:

2019 Series: 111 and 113.
2020 Series: 057, 065, 107, 110, 125, 133, 142 and 143.
2021 series: 002 and 003

WPGs Inforced 2020: Nil
WPGs cancelled 2020: 61
WPGs Inforced 2021: 01 and 02
WPGs cancelled 2021: Nil

PART – III

CORRECTIONS TO SAILING DIRECTIONS

NP38 West Coast of India Pilot (2019 Edition)

**India - West coast - JSW Jaigarh Port —
Outer anchorages**

213

Paragraph 7.99 1 lines 1-8 *Replace by:*

1 **Outer anchorages.** Designated anchorage areas are as follows:

- LNG vessels (17°18'·05N 73°02'·40E).
- LPG vessels (17°16'·52N 73°05'·47E).
- All vessels other than LPG and LNG (17°17'·05N 73°04'·45E).
- Emergency anchorage (17°18'·35N 73°09'·34E).

Indian Notice 21/207/20 **[NP38-No 37-Wk 01/21]**

PART – IV

MARINE INFORMATION

Nil

To accompany Pakistan Notice to Mariners 03/21

On BA Chart 1223

AUTOMATIC IDENTIFICATION SYSTEMS
AIS transmitters on aids to navigation are not shown on this chart. V-AIS will be shown. For details, see ADMIRALTY List of Radio Signals.

NP77. Vol D Edition 2020. Weekly Edition No. 1, Dated 07 January 2021.
 Last Updates: Weekly Edition No. 53, dated 31 December 2020.

D1555 NORTH COAST. PUERTO DE SANTANDER
 Remove from list; deleted

D2375-3 ES, I, 10420	- La Cabezuela. Industrial Plant. Pier. Head	36 31.71 N 6 15.54 W	Fl R 2.5s	7	3	Red truncated pyramidal tower 3	fl 0.5 *
D7314-3 OM, , 0208	- Main Channel. Dir Lt 279°	16 57.71 N 53 59.86 E	Dir WRG	15	10	Grey metal framework tower 12	F G277.7°-278.5°(0.8°). Al WG278.5°-278.7°(0.2°). F W278.7°-279.7°(1°). Al WR279.7°-280°(0.3°). F R280°-280.7°(0.7°) ..
	---	..	By day	..	4 *
D7335 OM, , 1280	JAZĪRAT TADMUR - Tadmur (AMNAS)	26 28.64 N 56 32.29 E	Fl(2)W 10s	60	23	White framework tower 24	fl 0.2, ec 1-6, fl 0.2, ec 8. W160.75°-133°(332.25°), W142.5°-156°(13.5°) ALRS Vol 2 Station 76680 *
	--	..	Racon