



PAKISTAN NOTICES TO MARINERS

WEEKLY EDITION 11

Notice: 43/21

20 MAR 2021

Copies of these Notices can be obtained gratis from Mercantile Marine Department and PN Chart Depot / NAVAREA IX Headquarters, 11 Liaquat Barracks Karachi. The same can be downloaded from web: www.paknavy.gov.pk/hydro.

CONTENTS

- I NOTICES TO MARINERS
- II REPRINTS OF RADIO NAVIGATIONAL WARNINGS
- III CORRECTIONS TO SAILING DIRECTIONS
- IV MARINE INFORMATION

Mariners are requested to inform the Hydrographic Department, Naval Headquarters, 11 Liaquat Barracks, Karachi, Pakistan, immediately on the discovery of new dangers, or suspected dangers to navigation and of changes or defects in aids to navigation noticed in NAVAREA IX and of shortcomings in PAK charts or publications.

Tel : + 92-21-48506151
+ 92-21-48506152
Fax : + 92-21-99201623
+ 92-21-35867737

E-mail : hydropk@paknavy.gov.pk
hydropk@gmail.com

Web : www.paknavy.gov.pk/hydro.

MUHAMMAD KHALID
Commodore
Hydrographer

Hydrographic Department, Naval Headquarters, 11 Liaquat Barracks, Karachi 75530, PAKISTAN

PART – I
NOTICES TO MARINERS

43/21 INDIA - West Coast - Wreck.

Chart PAK 57 [*previous update 173/20*] WGS84 DATUM

Insert  22° 23' 1N., 68° 42' 1E.

BA Chart 707 [*previous update 5773/20*] WGS84 DATUM

Insert  22° 23' 1N., 68° 42' 1E.

Source: Admiralty Notice to Mariners No. 1134/2021.

PART – II
RADIO NAVIGATIONAL WARNINGS

119/21. SELF CANCELLING. Cancel Navarea IX warnings 093 of 2021.

120/21. CENTRAL GULF. Qatar. Charts BA 2886, 2887 AND 2837. 'HALUL 51' seabed survey and debris removal operation will commence on 21 Mar in WP1 platform vicinity at position 25-55.03N, 052-42.65E within 500 meters radius. Mariners are requested to navigate with caution and give wide berth. Cancel this message on 272359 UTC Mar 2021

121/21. Southern Gulf. UAE. Charts BA 2443, 2444, 2889, 3178 and 3413 restricted area 200 meters radius established around the artificial reefs in following positions:

West of Das Island 25-08.16N 052-52.09E
West OF Zirkuh Island 24-51.65N 053-03.91E
East of Zirkuh Island 24-51.84N 053-05.54E

Anchoring strictly prohibited within the restricted areas and mariners are requested to navigate with caution. Cancel Navarea IX warning 114 of 2021

122/21. Pakistan. Ormara. Charts Pak 24, 33, 57 (INT 751), 58 (INT 7019), BA 38 and 707. Firing practice with live ammunition will be carried out on 25 and 26 Mar 2021 from 0300-1000 UTC in area bounded by following coordinates:

25-12N 064-30E
25-00N 064-30E
25-00N 064-48E
25-12N 064-48E

Ships and Craft are to keep well clear of assigned danger area on above specified schedule. Cancel this message on 261100 UTC Mar 2021

123/21. Southern Gulf (.) U A E (.) Charts BA 2837, 2858 and 2889. Seismic survey is being conducted in area bounded by:

Crew 209 area:
24-08.29N 052-00.10E
24-08.29N 052-12.20E
24-09.93N 052-12.20E
24-09.93N 052-14.38E
24-02.84N 052-14.38E
24-02.84N 052-00.10E

Crew 252 area:
Node spread area
25-23.80N 053-57.48E
25-23.50N 054-11.94E
25-18.45N 054-11.81E
25-18.76N 054-57.36E

Shooting area
25-26.96N 054-01.76E
25-26.81N 054-08.23E
25-15.35N 054-07.93E
25-15.49N 054-01.48E

Crew 253 area:
Source operation area
24-53.61N 053-05.47E
24-53.61N 053-17.92E

24-48.44N 053-17.92E
24-48.44N 053-05.47E

Receiver operation area
24-56.66N 053-09.11E
24-56.66N 053-14.32E
24-45.29N 053-14.32E
24-45.29N 053-09.11E

Mariners are advised to navigate with caution and to maintain a listening watch on channels 16/72 and 76. Cancel this message on 282359 UTC Mar 2021

124/21. Red Sea. Jeddah. Charts BA 158 and 4704. OSV Mehr reported stranded in position 21-37N 037-45E. Mariners are requested to navigate with caution and render assistance.

125/21. SELF CANCELLING. Cancel Navarea IX warnings 073 of 2021.

116/21. CENTRAL GULF. Qatar. Charts BA 2523, 2837, 2858, 2883 and 2886. 'Hakuryu 10' Rig will be located at appraisal well 'AP-30' in position 26-42.86N, 051-58.91E till 06 June 2021. Mariners are requested to navigate with caution and give wide berth.

117/21. CENTRAL GULF. Bahrain. Charts BA 2444, 2889, 3178 and 3179. Channel buoy No-3 drifted westward approx 1.8 NM from its charted position, current position is 25-06.55N, 053-01.06E. Mariners are requested to exercise caution while transit in the area.

118/21. SELF CANCELLING. Navarea IX Warnings inforce:

2019 Series: 126, 146, 381 and 393.
2020 Series: 004, 018, 035, 078, 150, 178, 184, 209, 215, 222, 225, 238, 266, 270, 336, 350, 379, 384, 387, 394, 406, 408, 409, 431, 449, 451 and 466.
2021 Series: 002, 003, 024, 033, 049, 050, 072, 073, 074, 076, 084, 086, 088, 093, 097, 098, 101, 109, 111, 113, 114, 115, 116 and 117.

COASTAL WARNING

031/21. PAKISTAN. Karachi Port. Charts PAK 5 (INT 7314), 30 (INT 7315), BA 40 and 58. PIDC channel beacon light at training wall in position 24-50.02N 066-58.03E reported non ops. Mariners cautioned.

032/21. SELF CANCELLING. Navigational Warnings Inforce:

2019 Series: 111 and 113.
2020 Series: 057, 065, 110, 125, 133 and 143.
2021 Series: 012, 022, 027 and 031

WPGs Inforced 2021: 11 and 14
WPGs cancelled 2021: 16

PART – III

CORRECTIONS TO SAILING DIRECTIONS

Nil

PART – IV

MARINE INFORMATION

Nil

NP77. Vol D Edition 2020. Weekly Edition No. 11, Dated 18 March 2021.
Last Updates: Weekly Edition No. 10, dated 11 March 2021.

D2023-7 PT, I, 55	- Vila do Conde. N Pier. Head	41 20-20 N 8 44-98 W	Fl R 4s	8	9	White column, red bands 8	<i>fl 1.</i> TE 2020	*
D2059-5 PT, I, 96-6	- Canal Principal de Navegação. N Commercial Wharf. N Pier. Head	40 39-22 N 8 43-63 W	Fl R 5s	6	4	White round tower, red bands 4	<i>fl 1.</i> TE 2020	*
D2665 PT, I, 747	- Porto Judeu. Pier. Head	38 38-90 N 27 07-02 W	Fl R 3s	8	3	White column, red bands 6	<i>fl 0-5.</i> TE 2020	*
D2684-1 PT, I, 830-1	- Areia Larga. Ldg Lts 082-2°. Rear. 20m from front	38 31-64 N 28 32-15 W	Iso R 4s	12	6	Red lantern on post 4	Shown when weather is suitable for approach. TE 2020	*
D2687-2 PT, I, 836	- Madalena. E Breakwater. Head	38 32-17 N 28 31-98 W	Fl(3)R 8s	11	10	White tower, red bands 7	<i>(fl 0-5, ec 1) x 2, fl 0-5, ec 4-5</i>	*
D2720 PT, I, 663	ILHA DESERTAS - Ilhéu Chão	32 35-37 N 16 32-75 W	LFl(2)W 15s	111	13	Tower and building 14	<i>fl 2, ec 2, fl 2, ec 9.</i> TE 2020	*
D2728 PT, I, 631	- Machico. São Roque	32 42-85 N 16 45-84 W	LFl WR 5s	11	W 9 R 7	White column, red bands 4	<i>fl 2.</i> R230°-265°(35°) over dangerous rock, W265°-230°(325°). TE 2020	*
D7296-782 *	Ras Shukheir LPG Terminal. Ldg Lts 057-6°. Front	28 07-20 N 33 17-03 E	G Lt	Post with blue and green bands	..	*
D7296-784 *	Ras Shukheir LPG Terminal. Ldg Lts 057-6°. Rear	28 07-28 N 33 17-19 E	G Lt	Post with blue and green bands	..	*
D7296-786 *	Ras Shukheir LPG Terminal. Ldg Lts 054-2°. Front	28 07-93 N 33 16-71 E	G Lt	Post with blue and green bands	..	*
D7296-788 *	Ras Shukheir LPG Terminal. Ldg Lts 054-4°. Rear	28 07-87 N 33 16-62 E	G Lt	Post with blue and green bands	..	*
D7296-79 *	Ras Shukheir LPG Terminal. Ldg Lts 116-85°. Front	28 08-13 N 33 16-69 E	F W	Post with blue and green bands	..	*
D7296-792 *	Ras Shukheir LPG Terminal. Ldg Lts 116-85°. Rear	28 08-14 N 33 16-67 E	F W	Post with blue and green bands	..	*
D7296-8	Ra's Shuqayr	28 07-80 N 33 16-43 E	Fl(3)W 20s	85	22	White □ on framework tower 17	..	*