



# PAKISTAN NOTICES TO MARINERS

## WEEKLY EDITION 32

Notice: 96(T)/21

14 AUG 2021

Copies of these Notices can be obtained gratis from Mercantile Marine Department and PN Chart Depot / NAVAREA IX Headquarters, 11 Liaquat Barracks Karachi. The same can be downloaded from web: [www.paknavy.gov.pk/hydro](http://www.paknavy.gov.pk/hydro).

### CONTENTS

- I NOTICES TO MARINERS
- II REPRINTS OF RADIO NAVIGATIONAL WARNINGS
- III CORRECTIONS TO SAILING DIRECTIONS
- IV MARINE INFORMATION

Mariners are requested to inform the Hydrographic Department, Naval Headquarters, 11 Liaquat Barracks, Karachi, Pakistan, immediately on the discovery of new dangers, or suspected dangers to navigation and of changes or defects in aids to navigation noticed in NAVAREA IX and of shortcomings in PAK charts or publications.

Tel : + 92-21-48506151  
+ 92-21-48506152  
Fax : + 92-21-99201623  
+ 92-21-35867737

E-mail : [hydropk@paknavy.gov.pk](mailto:hydropk@paknavy.gov.pk)  
[hydropk@gmail.com](mailto:hydropk@gmail.com)

Web : [www.paknavy.gov.pk/hydro](http://www.paknavy.gov.pk/hydro).

**MUHAMMAD WASIM**  
Captain Pakistan Navy  
Hydrographer

**Hydrographic Department, Naval Headquarters, 11 Liaquat Barracks, Karachi 75530, PAKISTAN**

**PART – I****NOTICES TO MARINERS****96(T)/21 GULF OF ADEN - Coastline. Depths.**

1. There have been changes to the coastline within the port of Tadjoura 11° 47'·005N., 42° 52'·821E.
2. There have been numerous changes to depths and coastline within the Port of Obock 11° 57'·719N., 43° 18'·274E.
3. Mariners are advised to navigate with caution in these areas.
4. These changes will be included in the next New Edition of BA Chart 265 to be published in late 2021.
5. Chart 264 will be updated by Notice to Mariners.  
(WGS84 DATUM)

**BA Chart affected - 265 (INT 7114)**

Source: Admiralty Notice to Mariners No. 3191(P)/2021.

**PART – II****RADIO NAVIGATIONAL WARNINGS**

**288/21. CENTRAL GULF.** Qatar. Charts BA 2523, 2837, 2883 and 2886. 'Hakuryu 12' rig will be moved on 08 Aug 21 by vessels 'Halul 70', 'Bourbon Liberty 304' and 'Bourbon Golf Liberty 211' from its current position 26-40.28N, 051-00.73E to position 26-43.54N, 051-55.01E. Mariners are requested to navigate with caution and give wide berth. Cancel this message on 150001 Aug 21.

**289/21. SOUTHERN GULF.** UAE. Charts BA 2837, 2858 and 2889. Seismic survey in progress till 15 Aug 2021 in area bounded by:

Crew 252 and 253 Area:  
Source Boundary  
25-16.76N 054-20.82E  
25-16.53N 054-28.54E  
24-56.60N 054-27.96E  
24-56.81N 054-20.26E  
Receiver Boundary  
25-13.77N 054-20.18E  
25-13.54N 054-29.56E  
24-59.54N 054-29.05E  
24-59.72N 054-19.69E

Crew 254 Area:  
Source Boundary  
24-35.08N 053-24.39E  
24-35.01N 053-29.72E  
24-24.06N 053-29.61E  
24-26.95N 053-27.71E  
24-29.05N 053-25.39E  
24-34.26N 053-25.44E  
Receiver Boundary  
24-31.83N 053-25.49E  
24-31.71N 053-33.13E  
24-21.94N 053-33.02E  
24-22.09N 053-30.10E  
24-24.06N 053-29.61E  
24-26.95N 053-27.71E  
24-29.05N 053-25.39E

Mariners are advised to navigate with caution and to maintain a listening watch on channels 16/72 and 76. Cancel this message on 152359 UTC Aug 21.

**290/21. SOUTHERN GULF.** UAE. Charts BA 2837, 2888 and 3174. Semi-submersible operation in progress by vessel 'Tai An Kou' at Saqr port special anchorage SP-02 on position 26-00.09N 055-58.86E till 13 Aug 21. Mariners are requested to navigate with caution and keep 0.5 NM exclusion zone around the above position. Cancel this message on 132359 UTC Aug 21.

**291/21. Southern GULF.** UAE. Charts BA 3779 and 3780. A fish farm has been installed in the following positions:

24-18.190N 052-39.631E  
24-18.195N 052-39.635E  
24-18.189N 052-39.644E  
24-18.184N 052-39.641E

Mariners are requested to navigate with caution while transiting this area.

**292/21. BAHRAIN.** Central Gulf. Charts BA 3736, 3737 and 3790. The construction operation of seabed excavation and pipeline laying activities of BAPCO terminal to Sitra port in the following bounded area:

26-09.96N 050-39.54E  
 26-10.23N 050-39.49E  
 26-10.21N 050-40.28E  
 26-09.78N 050-40.54E  
 26-09.71N 050-40.42E  
 26-09.86N 050-40.67E

Mariners are advised to navigate with caution, maintain listening watch on VHF channel 16/74 and take instructions as required from “Bahrain Port Control” and “BAPCO Wharf Control”. Cancel Navarea IX warning 408 of 2020.

**293/21. PAKISTAN.** Port Muhammad Bin Qasim. Charts PAK 5, 20 and BA 59. Navigation approach channel buoy No 2 drifted from charted position 24 33.93N 067 03.35E towards east. Mariners cautioned.

**294/21. PAKISTAN.** Gwadar. Charts PAK 27, 33, 57 (INT 751), 58 (INT 7019), BA 38 and 707. Firing practice with live ammunition will be carried out on 16 and 17 Aug 21. Details as under:

Position : 25-05.88N 062-22.27E  
 Time : 0300-1100 UTC  
 Firing Arcs : 130-220 Degree (Clockwise)  
 Safety Range : 13000 Meters

Ships and craft are to keep well clear of assigned danger area on above specified schedule. Cancel this message on 171200 UTC Aug 21.

**295/21. SELF CANCELLING.** Navarea IX Warnings inforce:

2019 Series: 126, 146, 381 and 393.  
 2020 Series: 004, 018, 035, 078, 150, 178, 209, 215, 222, 238, 266, 336, 350, 379, 387, 394, 406, 409, 449 and 451.  
 2021 Series: 024, 084, 086, 088, 109, 152, 176, 182, 203, 206, 221, 223, 224, 227, 234, 238, 241, 249, 250, 251, 254, 260, 265, 266, 276, 279, 288, 289, 291, 292, 293 and 294.

**COASTAL WARNING**

**078/21. PAKISTAN.** Port Muhammad Bin Qasim. Charts PAK 5, 20 and BA 59. Navigation approach channel buoy No 2 drifted from charted position 24 33.93N 067 03.35E towards east. Mariners cautioned.

**079/21. PAKISTAN.** Gwadar. Charts PAK 27, 33, 57 (INT 751), 58 (INT 7019), BA 38 and 707. Firing practice with live ammunition will be carried out on 16 and 17 Aug 21. Details as under:

Position : 25-05.88N 062-22.27E  
 Time : 0300-1100 UTC  
 Firing Arcs : 130-220 Degree (Clockwise)  
 Safety Range : 13000 Meters

Ships and craft are to keep well clear of assigned danger area on above specified schedule. Cancel this message on 171200 UTC Aug 21.

**080/21. SELF CANCELLING.** Navigational Warnings Inforce:

2019 Series: 111 and 113.  
 2020 Series: 057, 065, 110, 125, 133 and 143.  
 2021 Series: 075, 078 and 079.

WPGs Inforced 2021: 36 and 37

WPGs Cancelled 2021: Nil

**PART – III**

**CORRECTIONS TO SAILING DIRECTIONS**

**NP63 Persian Gulf Pilot (2021 Edition)**

**NP64 Red Sea and Gulf of Aden Pilot  
(2021 Edition)**

**United Arab Emirates - Jabal Az Zannah and  
Ar Ruways Port — Directions; buoy**

**Djibouti - Approaches to Djibouti —  
Arrival information; pilotage**

**173**

**322**

Paragraph 7.315 4 lines 1-4 *Replace by:*

Paragraph 14.57 1 lines 3-5 *Replace by:*

4 SSE of JBD-05A Light Buoy (S cardinal)  
(24°36'·80N 52°35'·76E), thence:

The pilots board in position 11°38'·34N 43°07'·77E  
for the main port. For vessels bound for Doraleh Oil  
(14.78)...

UKHO

[NP63-No 17-Wk 32/21]

French Notice 18/196/21

[NP64-No 1-Wk 32/21]

**PART – IV**

**MARINE INFORMATION**

Nil

NP77, Vol D Edition 2021. Weekly Edition No. 32, Dated 12 August 2021.  
 Last Updates: Weekly Edition No. 31, dated 05 August 2021.

<b>D2436-72</b>	- Jetty. Head	36 10-46 N	Q G 1s	4	1	..	<i>fl 0-3</i>
ES, II, 20362		5 23-01 W			2		
*	*	*	*	*	*	*	*
<b>D8580-66</b>	- Escravos River. SPM. No 4	5 28-00 N	Mo(4)W 15s	..	..	Superbuoy	..
	----	4 58-37 E	Horn Mo(G)	..	..	..	..
	----	..	15s	..	..	..	..
	----	..	Racon	..	..	..	ALRS Vol 2 Station 73022
*	*	*	*	*	*	*	*
<b>D8580-67</b>	- Escravos River. SPM. No 5	5 26-27 N	Mo(5)W 15s	..	..	Superbuoy	..
	----	4 58-27 E	Horn Mo(U)	..	..	..	..
	----	..	15s	..	..	..	..
	----	..	Racon	..	..	..	ALRS Vol 2 Station 73025
*	*	*	*	*	*	*	*