



# PAKISTAN NOTICES TO MARINERS

## WEEKLY EDITION 33

Notice: 97/21

21 AUG 2021

Copies of these Notices can be obtained gratis from Mercantile Marine Department and PN Chart Depot / NAVAREA IX Headquarters, 11 Liaquat Barracks Karachi. The same can be downloaded from web: [www.paknavy.gov.pk/hydro](http://www.paknavy.gov.pk/hydro).

### CONTENTS

- I NOTICES TO MARINERS
- II REPRINTS OF RADIO NAVIGATIONAL WARNINGS
- III CORRECTIONS TO SAILING DIRECTIONS
- IV MARINE INFORMATION

Mariners are requested to inform the Hydrographic Department, Naval Headquarters, 11 Liaquat Barracks, Karachi, Pakistan, immediately on the discovery of new dangers, or suspected dangers to navigation and of changes or defects in aids to navigation noticed in NAVAREA IX and of shortcomings in PAK charts or publications.

Tel : + 92-21-48506151  
+ 92-21-48506152  
Fax : + 92-21-99201623  
+ 92-21-35867737

E-mail : [hydropk@paknavy.gov.pk](mailto:hydropk@paknavy.gov.pk)  
[hydropk@gmail.com](mailto:hydropk@gmail.com)

Web : [www.paknavy.gov.pk/hydro](http://www.paknavy.gov.pk/hydro).

**MUHAMMAD WASIM**  
Captain Pakistan Navy  
Hydrographer

**Hydrographic Department, Naval Headquarters, 11 Liaquat Barracks, Karachi 75530, PAKISTAN**

**PART – I**  
**NOTICES TO MARINERS**

**97/21 EGYPT - Red Sea Coast - Wrecks.**

**BA Chart 2374 (INT 7134)** [ *previous update 3019/21* ] WGS84 DATUM

Insert



28° 19'·21N., 33° 08'·00E.

28° 18'·82N., 33° 07'·74E.

Source: Admiralty Notice to Mariners No. 3249/2021.

**PART – II**  
**RADIO NAVIGATIONAL WARNINGS**

**296/21. SOUTHERN GULF.** UAE. Charts BA 2837, 2858 and 2889. Seismic survey in progress till 22 Aug 2021 in area bounded by:

Crew 252 And 253 Area:

Source Boundary

25-16.89N 054-16.62E

25-16.65N 054-24.96E

24-56.67N 054-24.44E

24-56.88N 054-16.18E

Receiver Boundary

25-13.89N 054-17.87E

25-13.66N 054-26.16E

24-59.62N 054-25.61E

24-59.96N 054-15.46E

24-09.80N 054-15.72E

Crew 254 Area:

Source Operation Area

24-30.13N 053-29.80E

24-30.06N 053-34.06E

24-18.73N 053-33.83E

24-18.77N 053-30.76E

24-24.06N 053-29.61E

Cable Operation Area

24-31.83N 053-25.49E

24-31.77N 053-29.40E

24-26.92N 053-29.30E

24-26.76N 053-37.47E

24-21.91N 053-37.37E

24-22.09N 053-30.10E

24-24.06N 053-29.61E

24-26.95N 053-27.71E

24-29.05N 053-25.39E

Mariners are advised to navigate with caution and to maintain a listening watch on channels 16/72 and 76. Cancel this message on 222359 UTC Aug 21.

**297/21. CENTRAL GULF.** Bahrain. Charts BA 2837, 2883, 2886, 2887 and 2889. ‘Energy Emerger’ rig will be moved by vessels ‘Allianz Wrangler’, ‘Bourbon Nilgan’ and ‘Bourban Liberty’ from 17 Aug 21. The towage will commence from its current position 27-06.65N, 050-55.52E to UAE in position 25-28.28N, 055-28.68E. Mariners are requested to navigate with caution, give wide berth of 500 meters and monitoring VHF channel 16. Cancel this message on 202359 UTC Aug 21. Cancel Navarea IX warning 227 of 2021.

**298/21. SOUTHERN GULF.** UAE. Charts BA 2837, 2858 and 2889. Seismic survey in progress till 22 Aug 2021 in area bounded by:

Crew 252 And 253 Area:

Source Boundary

25-16.89N 054-16.62E

25-16.65N 054-24.96E

24-56.67N 054-24.44E

24-56.88N 054-16.18E

Receiver Boundary

25-13.89N 054-17.87E

25-13.66N 054-26.16E

24-59.62N 054-25.61E  
 24-59.96N 054-15.46E  
 25-09.80N 054-15.72E

Crew 254 Area:  
 Source Operation Area  
 24-30.13N 053-29.80E  
 24-30.06N 053-34.06E  
 24-18.73N 053-33.83E  
 24-18.77N 053-30.76E  
 24-24.06N 053-29.61E  
 Cable Operation Area  
 24-31.83N 053-25.49E  
 24-31.77N 053-29.40E  
 24-26.92N 053-29.30E  
 24-26.76N 053-37.47E  
 24-21.91N 053-37.37E  
 24-22.09N 053-30.10E  
 24-24.06N 053-29.61E  
 24-26.95N 053-27.71E  
 24-29.05N 053-25.39E

Mariners are advised to navigate with caution and to maintain a listening watch on channels 16/72 and 76. Cancel this message on 222359 UTC Aug 21. Cancel Navarea IX warning 296 of 2021.

- 299/21. APPROACHES TO JUBAIL.** Saudi Arabia. Charts BA 3719, 3775 and 3788. Obstruction-foul ground exists in position 27-16.197N 049-55.322E due to lost anchor and chain. Mariners are advised not to anchor close to this position.
- 300/21. CENTRAL GULF.** Bahrain. Charts BA 3883, 2886 and 3788. Dangerous uncharted yellow buoy reported adrift in position 26-51.95N, 050-51.46E at north of Hayr Abu Amamah. Mariners are requested to navigate with caution. Cancel this message 22 Aug 2021.
- 301/21. PAKISTAN.** Karachi. Charts PAK 33, 57 (INT 751), 58 (INT 7019), BA 38 and 707. Karachi Radio (Navtex Station) in position 24-52.78N 067-09.94E inoperative. All navigational warnings are being transmitted on international Safetynet and available on website [www.paknavy.gov.pk/hydro](http://www.paknavy.gov.pk/hydro) or [www.hydrography.paknavy.gov.pk/navarea-ixiwarnings](http://www.hydrography.paknavy.gov.pk/navarea-ixiwarnings) Mariners cautioned. Cancel Navarea IX warning 241 of 2021.
- 302/21. SELF CANCELLING.** Navarea IX Warnings inforce:
  - 2019 Series: 126, 146, 381 and 393.
  - 2020 Series: 004, 018, 035, 078, 150, 178, 209, 215, 222, 238, 266, 336, 350, 379, 387, 394, 406, 409, 449 and 451.
  - 2021 Series: 024, 084, 086, 088, 109, 152, 176, 182, 203, 206, 221, 223, 224, 234, 238, 249, 250, 251, 254, 260, 265, 266, 276, 279, 291, 292, 293, 298, 299, 300 and 301.

**COASTAL WARNING**

- 081/21. SELF CANCELLING.** Navigational Warnings Inforce:
  - 2019 Series: 111 and 113.
  - 2020 Series: 057, 065, 110, 125, 133 and 143.
  - 2021 Series: 075 and 078.

WPGs Inforced 2021: 36  
 WPGs Cancelled 2021: 37

**PART – III**

**CORRECTIONS TO SAILING DIRECTIONS**

**NP63 Persian Gulf Pilot (2021 Edition)**

**United Arab Emirates - Dubai - Palm Deira —  
Development; directions**

147

Paragraph 7.58 3 lines 4–6 *Replace by:*

NW of the Palm Deira development (25°21'·64N  
55°13'·81E) (7.3), marked close NW by PD–NC  
Light Buoy (N cardinal).

Corr. DMCA Notice 04–Jun–21

[NP63–No 18–Wk 33/21]

**United Arab Emirates - Dubai - Al Ḥamrīyah —  
Speed restriction**

149–150

Paragraph 7.88 1–2 *Replace by:*

1 **Description.** Al Ḥamrīyah (25°17'·85N 55°19'·78E)  
lies within an area of reclaimed land which fronts the  
coast. The entrance and basin are both dredged to  
6 m (1979). The harbour is administered by Dubai  
Port Authority. There is a VTS; see *ADMIRALTY List  
of Radio Signals Volume 6(8)*.

**Speed** is restricted to 5 kn within the entrance  
channel and harbour basin.

2 **Directions.** The harbour is entered from the N  
through a buoyed channel (25°18'·95N 55°19'·92E) at  
the base of the Palm Deira Development (7.3).

Corr. DMCA Notice 26–May–21

[NP63–No 19–Wk 33/21]

**United Arab Emirates - West-south-west of  
Shārjah - Palm Deira — Development**

151

Paragraph 7.98 1 *Replace by:*

1 The Palm Deira development (7.3), to the SW of  
Shārjah, extends up to 10 miles from the shore  
between Mīnā' Khalid and Mīnā' Rashid, 7 miles SW;  
vessels are advised to navigate with caution in or  
near this area. For the latest information, contact the  
Port Authority and consult the latest *ADMIRALTY  
Notices to Mariners*.

Corr. DMCA Notice 04–Jun–21

[NP63–No 20–Wk 33/21]

**United Arab Emirates - Dubai - Mīnā' Rashid —  
Speed restrictions**

152

*After* Paragraph 7.115 1 line 6 *Insert* including Heading:

**Regulations concerning entry  
7.115a**

1 **Speed** is restricted to 5 kn within Mīnā' Rashid,  
Dubai Maritime City Basin and Dubai Dry Docks.

Corr. DMCA Notice 26–May–21

[NP63–No 21–Wk 33/21]

**United Arab Emirates - Jebel Ali —  
Restricted areas; speed restriction**

157

Paragraph 7.168 1 including existing Section IV Notice  
Week 31/21 *Replace by:*

1 **Restricted areas.** Entry is restricted into:  
An area (25°03'·93N 55°05'·38E) surrounding the  
DEWA power station (7.172);  
An area, marked by light buoys (special),  
surrounding Palm Jebel Ali (25°00'·80N  
54°59'·04E) and Dubai Waterfront (24°56'·69N  
54°54'·27E); see 7.3 and 7.170.

*After* Paragraph 7.168 1 line 4 *Insert:*

**Regulations concerning entry  
7.168a**

1 **Speed** is restricted to 5 kn within the entrance  
channel and harbour basins.

Corr. DMCA Notice 26–May–21

[NP63–No 22–Wk 33/21]

**United Arab Emirates - Jebel Ali -  
Hassyan Clean Coal Power Plant —  
Speed restriction**

158

*After* Paragraph 7.187 1 line 3 *Insert:*

**Speed** is restricted to 5 kn within the entrance  
channel and harbour.

Corr. DMCA Notice 26–May–21

[NP63–No 23–Wk 33/21]

**PART – IV**

**MARINE INFORMATION**

Nil

NP77, Vol D Edition 2021. Weekly Edition No. 33, Dated 19 August 2021.  
 Last Updates: Weekly Edition No. 32, dated 12 August 2021.

<b>D1532-2</b> ES. I. 00805	- Ría. Dársena de Udondo. Jetty. Head	43 18-88 N 2 59-53 W	Q R	7	1 Red post 5	..	*
<b>D1532-25</b> ES. I. 00806	- Ría. Dársena de Udondo. Breakwater. Head	43 18-84 N 2 59-49 W	Fl(2+1)R 10s	7	1 Red post, green band 5	fl 0-5, ec 0-7, fl 0-5, ec 2-1, fl 0-5, ec 5-7	*
<b>D1534-12</b> ES. I. 00880	- Ria. Canal de Deusto	43 16-89 N 2 58-08 W	Q R 1s	10	1 Red tripod, on hut 8	<b>TE; replaced by light buoy (T) 2021</b>	*
<b>D1732</b> ES. I. 03760	- <b>Punta Laxe</b>	43 13-93 N 9 00-67 W	Fl(5)W 20s	64	<b>20</b> White truncated conical tower 11	(fl 0-1, ec 2-4) x 4, fl 0-1, ec 9-9. <b>Irreg (T) 2021</b>	*
<b>D1864</b> ES. I. 04700	- Río Lerez. Pontevedra. S Training Wall. W Head	42 24-88 N 8 41-24 W	Fl G 5s	4	3 Green post	fl 0-5	*