

PAKISTAN NOTICES TO MARINERS

WEEKLY EDITION 02

Notice: 05/22

15 JAN 2022

Copies of these Notices can be obtained gratis from Mercantile Marine Department and PN Chart Depot / NAVAREA IX Headquarters, 11 Liaquat Barracks Karachi. The same can be downloaded from web: www.paknavy.gov.pk/hydro.

CONTENTS

I NOTICES TO MARINERS

II REPRINTS OF RADIO NAVIGATIONAL WARNINGS

III CORRECTIONS TO SAILING DIRECTIONS

IV MARINE INFORMATION

Mariners are requested to inform the Hydrographic Department, Naval Headquarters, 11 Liaquat Barracks, Karachi, Pakistan, immediately on the discovery of new dangers, or suspected dangers to navigation and of changes or defects in aids to navigation noticed in NAVAREA IX and of shortcomings in PAK charts or publications.

Tel : +92-21-48506151 +92-21-48506152

Fax : +92-21-99201623

+ 92-21-35867737

E-mail: hydropk@paknavy.gov.pk

hydrpk@gmail.com

Web: www.paknavy.gov.pk/hydro.

MUHAMMAD WASIM Captain Pakistan Navy Hydrographer

Hydrographic Department, Naval Headquarters, 11 Liaquat Barracks, Karachi 75530, PAKISTAN

27° 32′·2N., 52° 33′·1E.

PART - I

NOTICES TO MARINERS

05/22 IRAN - NM Block.

BA Chart 2883 (INT 7260) (Panel A, Bandar-e Pars (Port of Asaluyeh)) [previous update 4973/21] WGS84 DATUM

Insert the accompanying block, centred on:

Source: Admiralty Notice to Mariners No. 118/2022.

<u>PART – II</u> RADIO NAVIGATIONAL WARNINGS

013/22. SOUTHERN GULF. UAE. Charts BA 2837, 2858 and 2889. Seismic survey in progress till 16 Jan 2022 in areas bounded by:

Receiver Boundary 25-01.75N 053-25.90E 25-01.64N 053-31.87E 24-56.54N 053-31.78E 24-56.64N 053-25.79E

Source Boundary 25-01.74N 053-26.00E 25-01.65N 053-32.13E 24-51.97N 053-31.50E

24-51.97N 053-31.50E 24-52.06N 053-25.79E

Fishing, anchoring and diving operations are strictly prohibited in survey areas. Mariners are advised to navigate with caution and maintain listening watch on channels 16/72. Cancel this message on 162359 UTC Jan 22.

- 014/22. SELF CANCELLING. Survey operation completed. Cancel Navarea IX warning 461 of 2021.
- **015/22. ARABIAN GULF.** Saudi Arabia Port Ra's Al Khair. Chart BA 2847, 2882 and 3775. Channel buoy RAZ 26 in position 26-35.96N 050-13.21E reported missing. Mariners cautioned.
- 016/22. SELF CANCELLING. Cancel Navarea IX warnings 176 and 265 of 2021.
- 017/22. SELF CANCELLING. Cancel Navarea IX warnings 495 and 502 of 2021.
- **018/22. RED SEA.** Saudi Arabia. BA Charts 158, 2658 and 2659. Firing practice in progress till 13 Jan 2022 in area bounded by following coordinates:

21-06.00N 038-58.50E 21-05.58N 039-07.00E 21-13.40N 038-58.50E 21-13.50N 039-06.20E

Ships and craft are to keep well clear of assigned danger area on above specified schedule. Cancel this message on 132359 UTC Jan 2022.

- **019/22. SELF CANCELLING.** Cancel Navarea IX warning 006 of 2022.
- **020/22. CENTRAL GULF.** Bahrain. BA Charts 3736 and 3737. Local Charts 5004 and 1501. Following buoys have been temporarily moved due to dredging operation (Bahrain steel jetty area) from their current location to following new positions:
 - a. BS-1
 b. BS-3
 c. BS-5
 26-11.04N 050-41.55E
 26-11.28N 050-41.55E
 26-11.51N 050-41.42E
 - d. BS-7 26-11.63N 050-41.37E

Mariners are requested to navigate with caution. Cancel Navarea IX warning 416 of 2021.

- **021/22. CENTRAL GULF.** Qatar. Charts BA 2523, 2837, 2858, 2886 and 3950. 24 hours ROV campaign in progress by vessel 'DSV Halul 49' for several platforms in the area bounded by following coordinates:
 - a. 26-43.55N 051-50.86E
 - b. 26-43.55N 052-04.14E
 - c. 26-26.81N 052-04.14E
 - d. 26-26.81N 051-50.86E

Mariners are requested to navigate with caution and give wide berth. Cancel Navarea IX warning 088 of 2021

022/22. PAKISTAN. Karachi. Charts PAK 5, 33, 57 (INT 751), BA 58 and 707.

Marine Oil Spill and Search and Rescue Exercise - Barracuda

Naval and PMSA units alongwith other agencies will carry out exercise using booms, skimmers and other equipment on 13 Jan 22 between 0500–1030 UTC in area bounded by:

24-46.50N 066-43.00E 24-46.50N 066-54.00E 24-36.50N 066-54.00E 24-36.50N 066-43.00E

Vessels are requested to keep clear of exercise area. Cancel this message on 131130 UTC Jan 2022.

- 023/22. SELF CANCELLING. Cancel Navarea IX warnings 266 and 350 of 2020.
- 024/22. SELF CANCELLING. Buoy replaced at charted position. Cancel Navarea IX warning 517 of 2021.
- **025/22. IRAN.** Charts BA 2837, 2847 and 2883. Light vessel of 'Motaf' reported missing from its charted position and has been replaced by another light vessel. The last known position of missed vessel is 27-33.24N, 051-25.90E. Mariners are requested to navigate with extreme caution, keep sharp lookout, report to port control or Bushehr MRCC if found. Cancel this message 17 Jan 2022.
- 026/22. SELF CANCELLING. Navigational Warnings Inforce:

2020 series: 004

2021 series: 024, 086, 109, 152, 223, 224, 251, 292, 323, 336, 340, 364, 368, 372, 377, 397, 398, 399, 408, 421, 441, 445,

448, 453, 472, 475, 477, 481, 490, 491, 492, 503, 506, 510, 513 and 516

2022 series: 007, 011, 013, 015, 020, 021 and 025

COASTAL WARNING

- 006/22. SELF CANCELLING. Survey operation completed. Cancel coastal warning 130 of 2021.
- **007/22. PAKISTAN.** Karachi. Charts PAK 5, 33, 57 (INT 751), BA 58 and 707.

Marine Oil Spill and Search and Rescue Exercise - Barracuda

Naval and PMSA units alongwith other agencies will carry out exercise using booms, skimmers and other equipment on 13 Jan 22 between 0500–1030 UTC in area bounded by:

24-46.50N 066-43.00E

24-46.50N 066-54.00E

24-36.50N 066-54.00E

24-36.50N 066-43.00E

Vessels are requested to keep clear of exercise area. Cancel this message on 131130 UTC Jan 2022.

008/22. SELF CANCELLING. Navigational Warnings Inforce:

2020 Series: 143.

2021 Series: 095, 096, 127, 136 and 150.

2022 Series: 004.

WPGs Inforced 2021: 66 WPGs Cancelled 2021: Nil WPGs Inforced 2022: 03 WPGs Cancelled 2022: 02

PART - III

CORRECTIONS TO SAILING DIRECTIONS

NP63 Persian Gulf Pilot (2021 Edition)

United Arab Emirates – Umm al Qaywayn to Dubai — Directions; buoy

147

Paragraph 7.58 $\it s$ lines 4-6 including existing Section IV Notice Week 33/21 *Replace by:*

NW of the Palm Deira development (25°21'·64N 55°13'·81E) (7.3), marked close NW by PD-NC Light Buoy (N cardinal). And:


Light Buoy (N cardinal). And:

NW of a light buoy (isolated danger) (25°22′·65N 55°11′·70E), marking a shoal patch of unknown extent. Vessels are advised to give the buoy a wide berth.

Dubai Maritime City Authority (DMCA) NAV G008/21 [NP63-No 37-Wk 02/22]

<u>PART – IV</u> MARINE INFORMATION

Nil



Block for BA Chart No 2883

NP77, Vol D Edition 2021. Weekly Edition No. 2, Dated 13 January 2022. *Last Updates: Weekly Edition No. 1, dated 06 January 2022.*

47 17·21 N 2 10·25 W Iso R 1·2s 3 3 Red \square on red beacon ... D1130-31 - Bridge. No 26

FR, L1, 36220