



PAKISTAN NOTICES TO MARINERS

WEEKLY EDITION 05

Notice: 18/22

05 FEB 2022

Copies of these Notices can be obtained gratis from Mercantile Marine Department and PN Chart Depot / NAVAREA IX Headquarters, 11 Liaquat Barracks Karachi. The same can be downloaded from web: hydrography.paknavy.gov.pk.

CONTENTS

- I NOTICES TO MARINERS
- II REPRINTS OF RADIO NAVIGATIONAL WARNINGS
- III CORRECTIONS TO SAILING DIRECTIONS
- IV MARINE INFORMATION

Mariners are requested to inform the Hydrographic Department, Naval Headquarters, 11 Liaquat Barracks, Karachi, Pakistan, immediately on the discovery of new dangers, or suspected dangers to navigation and of changes or defects in aids to navigation noticed in NAVAREA IX and of shortcomings in PAK charts or publications.

Tel : + 92-21-48506151
+ 92-21-48506152
Fax : + 92-21-99201623
+ 92-21-35867737

E-mail : hydropk@paknavy.gov.pk
hydropk@gmail.com

Web : hydrography.paknavy.gov.pk.

MUHAMMAD WASIM
Captain Pakistan Navy
Hydrographer

Hydrographic Department, Naval Headquarters, 11 Liaquat Barracks, Karachi 75530, PAKISTAN

PART – I
NOTICES TO MARINERS

18*/22 UNITED ARAB EMIRATES - Buoyage. Legend.

BA Chart 2887 (INT 7232) [*previous update 5078/21*] WGS84 DATUM

Delete legend, (*marked by buoys*), centred on: 25° 35′.6N., 55° 17′.7E.

BA Chart 2888 (INT 7199) [*previous update 5282/21*] WGS84 DATUM

Delete legend, (*marked by buoys*), centred on: 25° 35′.6N., 55° 17′.7E.

BA Chart 2889 (INT 7211) [*previous update 4596/21*] WGS84 DATUM

Delete legend, (*marked by buoys*), centred on: 25° 35′.6N., 55° 17′.7E.

BA Chart 3175 (INT 7212) [*previous update 30/22*] WGS84 DATUM

Delete  *FLY.4s* 25° 35′.06N., 55° 21′.57E.
 25° 35′.23N., 55° 20′.42E.
 25° 35′.48N., 55° 19′.70E.
 25° 35′.68N., 55° 18′.58E.
 25° 35′.93N., 55° 17′.57E.
 25° 36′.16N., 55° 16′.52E.
 25° 36′.44N., 55° 15′.46E.
 25° 36′.60N., 55° 14′.52E.
 25° 36′.88N., 55° 13′.45E.

Source: Admiralty Notice to Mariners No. 400*/2022.

PART – II
RADIO NAVIGATIONAL WARNINGS

041/22. CENTRAL GULF. Qatar. Charts BA 2523, 2837, 2886 and 3950. Debris survey in progress by vessels Halul 61 and Halul 40 in areas bounded by following coordinates:

26-21.12N 051-24.60E
 25-37.47N 052-14.25E
 25-18.83N 051-40.05E
 25-28.90N 051-35.42E
 25-50.75N 051-37.02E
 25-54.93N 051-41.48E
 26-00.55N 051-28.30E
 26-13.03N 051-16.50E

Mariners are requested to navigate with caution and keep clear from survey vessels.

042/22. SOUTHERN GULF. UAE. Charts BA 2837, 2858 and 2889. Seismic survey in progress till 06 Feb 2022 in areas bounded by:

Receiver Boundary
 25-01.67N 053-30.85E
 25-01.57N 053-36.77E
 24-56.44N 053-36.66E
 24-56.54N 053-30.73E

Source Boundary
 25-01.65N 053-31.06E
 25-01.56N 053-36.60E
 24-51.88N 053-36.41E
 24-51.99N 053-30.84E

Fishing, anchoring and diving operations are strictly prohibited in survey areas. Mariners are advised to navigate with caution and maintain listening watch on channels 16/72. Cancel this message on 062359 UTC Feb 22.

043/22. CENTRAL GULF. Qatar. BA 2523, 2847, 2858 and 2886. Self propelled rig barge QMS Nouf will be moved on 31 Jan 22 with support vessel BL 306 from its current position 25-53.80N, 051-38.50E to position 26-38.33N, 051-57.10E. Mariners are requested to navigate with caution. Cancel this message 02 Feb 2022.

044/22. ARABIAN SEA. Pakistan. Charts 33, 57(INT 751) and BA 707. Submarine cable repair operation in progress by C/S Maram between 23-41.49N 065-53.79E and 23-46.89N 066-00.23E. Ship is restricted in her ability to manoeuvre. Mariners are requested to navigate with caution and give wide berth.

045/22. SOUTHERN GULF. UAE. Charts BA 2443, 2444, 2889 and 3178. Mubarraz approach buoy in position 24-57.33N, 053-18.36E reported unlit. Mariners are requested to navigate with caution.

- 046/22. SOUTHERN GULF.** UAE (Das Island). Charts BA 2444, 2886, 2889 and 3413. Special mark buoy No.2 in position 25-07.70N, 052-54.56E reported missing. Mariners are requested to navigate with caution.
- 047/22. CENTRAL GULF.** Qatar. BA 2523, 2847, 2858 and 2886. Self propelled rig barge QMS Nouf moving operation in progress with support vessel BL 306 from its current position 25-53.80N, 051-38.50E to position 26-38.33N, 051-57.10E. Mariners are requested to navigate with caution. Cancel this message on 07 Feb 2022.

- 048/22. PAKISTAN.** Approaches to Karachi. Charts PAK 5 (INT 7314), 33, 57 (INT 751), BA 39 and 58. Firing practice with live ammunition will be carried out on 07 and 08 Feb 22. Details as under:

Position : 24-48.38N 066-57.35E
 Safety Range : 13000 Meters
 Firing Arc : 225-270 Degree (Clockwise)
 Time : 0300-1300 UTC

Ships and craft are to keep well clear of assigned danger area on above specified schedule. Cancel this message on 081500 UTC Feb 22.

- 049/22. SOUTHERN GULF.** Dubai (Mina Jebel Ali). Charts BA 2837, 2887, 2889, 3176 and 3739. Jebel Ali light buoy in position 25-10.61N 054-52.31E reported unlit. Mariners are requested to navigate with caution.

- 050/22. SELF CANCELLING.** Survey operation completed. Cancel Navarea IX warning 472 of 2021.

- 051/22. SELF CANCELLING.** Navigational Warnings Inforce:

2020 series: 004
 2021 series: 024, 086, 109, 152, 223, 224, 251, 292, 323, 336, 340, 364, 368, 372, 377, 397, 398, 399, 408, 421, 445, 448, 453, 475, 477, 481, 490, 491, 492, 503, 510 and 513.
 2022 series: 015, 020, 021, 027, 030, 033, 037, 038, 039, 041, 042, 044, 045, 046, 047, 048 and 049

COASTAL WARNING

- 014/22. ARABIAN SEA.** Pakistan. Charts 33, 57(INT 751) and BA 707. Submarine cable repair operation in progress by C/S Maram between 23-41.49N 065-53.79E and 23-46.89N 066-00.23E. Ship is restricted in her ability to manoeuvre. Mariners are requested to navigate with caution and give wide berth.

- 015/22. PAKISTAN.** Approaches to Karachi. Charts PAK 5 (INT 7314), 33, 57 (INT 751), BA 39 and 58. Firing practice with live ammunition will be carried out on 07 and 08 Feb 22. Details as under:

Position : 24-48.38N 066-57.35E
 Safety Range : 13000 Meters
 Firing Arc : 225-270 Degree (Clockwise)
 Time : 0300-1300 UTC

Ships and craft are to keep well clear of assigned danger area on above specified schedule. Cancel this message on 081500 UTC Feb 22.

- 016/22. SELF CANCELLING.** Navigational Warnings Inforce:

2020 Series: 143.
 2021 Series: 095, 096, 127 and 136.
 2022 Series: 012, 014 and 015.

WPGs Inforced 2021: Nil
 WPGs Cancelled 2021: 66
 WPGs Inforced 2022: 04 and 05
 WPGs Cancelled 2022: 03

PART – III

CORRECTIONS TO SAILING DIRECTIONS

Nil

PART – IV

MARINE INFORMATION

Nil

NP77, Vol D Edition 2021. Weekly Edition No. 5, Dated 03 February 2022.
 Last Updates: Weekly Edition No. 4, dated 27 January 2022.

D2616 MA., 17800 ES, 1, 13760 FR, L2, 17940 *	Sidi Ifni	29 22-81 N 10 10-69 W *	Fl(3+1)W 30s	57	25 Yellow square tower on building 13	(fl 0-3, ec 3-4) x 2, (fl 0-3, ec 11) x 2. FR lights on 4 posts 2-2M to the ENE. TE 2021	*
D3085-4 FR, L2, 21652 *	- Port Kamsar. KCT Jetty. NW Corner *	10 39-05 N 14 37-14 W *	Fl R 3s *	*
D3085-5 FR, L2, 21654 *	- Port Kamsar. KCT Jetty. SW Corner *	10 39-03 N 14 37-14 W *	Fl R 3s *	*
D3086-4 FR, L2, 21642 *	- Port Kamsar. GAC Jetty. NA-01 *	10 38-16 N 14 37-84 W *	Fl(3)R 5s *	..	5 Red □ on beacon	..	*
D3086-5 FR, L2, 21644 *	- Port Kamsar. GAC Jetty. NA-02 *	10 38-04 N 14 37-88 W *	Fl(3)G 5s *	..	5 Green △ on beacon	..	*
D7354-2	- Lee Breakwater. Head. No 2	25 22-01 N 55 22-24 E	Fl W 3s *	15	7 Red and white metal framework tower 12	..	