



PAKISTAN NOTICES TO MARINERS

WEEKLY EDITION 07

Notice: 21(P)/22

19 FEB 2022

Copies of these Notices can be obtained gratis from Mercantile Marine Department and PN Chart Depot / NAVAREA IX Headquarters, 11 Liaquat Barracks Karachi. The same can be downloaded from web: hydrography.paknavy.gov.pk.

CONTENTS

- I NOTICES TO MARINERS
- II REPRINTS OF RADIO NAVIGATIONAL WARNINGS
- III CORRECTIONS TO SAILING DIRECTIONS
- IV MARINE INFORMATION

Mariners are requested to inform the Hydrographic Department, Naval Headquarters, 11 Liaquat Barracks, Karachi, Pakistan, immediately on the discovery of new dangers, or suspected dangers to navigation and of changes or defects in aids to navigation noticed in NAVAREA IX and of shortcomings in PAK charts or publications.

Tel : + 92-21-48506151
+ 92-21-48506152
Fax : + 92-21-99201623
+ 92-21-35867737

E-mail : hydropk@paknavy.gov.pk
hydropk@gmail.com

Web : hydrography.paknavy.gov.pk.

MUHAMMAD WASIM
Captain Pakistan Navy
Hydrographer

Hydrographic Department, Naval Headquarters, 11 Liaquat Barracks, Karachi 75530, PAKISTAN

PART – I**NOTICES TO MARINERS****21(P)/22 UNITED ARAB EMIRATES - Anchorage areas. Light. Depths.**

1. Anchorage areas have been established, bounded by the following positions:

Sharjah A

25° 28'·20N., 55° 16'·30E.

25° 24'·90N., 55° 16'·30E.

25° 24'·90N., 55° 19'·00E.

25° 28'·20N., 55° 19'·00E.

Sharjah B

25° 30'·10N., 55° 11'·90E.

25° 27'·50N., 55° 11'·90E.

25° 27'·50N., 55° 14'·80E.

25° 30'·10N., 55° 14'·80E.

Sharjah C

25° 32'·70N., 55° 15'·10E.

25° 30'·10N., 55° 15'·10E.

25° 30'·10N., 55° 17'·20E.

25° 32'·70N., 55° 17'·20E.

2. The former anchorage areas, bounded by the following positions, have been removed:

Alpha

25° 31'·79N., 55° 19'·20E.

25° 30'·00N., 55° 17'·60E.

25° 29'·00N., 55° 19'·15E.

25° 30'·80N., 55° 20'·69E.

Bravo

25° 32'·25N., 55° 16'·09E.

25° 31'·55N., 55° 15'·50E.

25° 30'·70N., 55° 16'·75E.

25° 32'·25N., 55° 18'·07E.

Mīnā' Khalid / Shārjah

25° 27'·98N., 55° 16'·00E.

25° 25'·01N., 55° 16'·00E.

25° 25'·01N., 55° 18'·08E.

25° 27'·98N., 55° 18'·08E.

3. The light in position 25° 22'·02N., 55° 22'·24E. has been amended to *Fl.3s7M*.
4. Depths in the approach channel to Mīnā' Khalid, in the vicinity of 25° 23'·01N., 55° 20'·98E. have been reported to be deeper than charted.
5. Mariners are advised to navigate with caution in the area and consult the local port authorities for the latest information.
6. These changes will be included in the next New Edition of BA Chart 3412 to be published early 2022.
7. BA Charts 2887, 2889, 3175, 3176 and 3405 will be updated by Notice to Mariners.
(WGS84 DATUM)

BA Chart affected - 3412 (INT 7219)

Source: Admiralty Notice to Mariners No. 615(P)/2022.

PART – II**RADIO NAVIGATIONAL WARNINGS****065/22. SOUTHERN GULF. UAE. Charts BA 2837, 2858 and 2889. Seismic survey in progress till 20 Feb 2022 in areas bounded by:**

Receiver Boundary

25-01.62N 053-33.86E

25-01.51N 053-39.82E

24-56.39N 053-39.71E

24-56.48N 053-33.76E

Source Boundary

25-01.62N 053-33.86E

25-01.52N 053-39.61E

24-53.16N 053-39.45E

24-53.26N 053-33.70E

Fishing, anchoring and diving operations are strictly prohibited in survey areas. Mariners are advised to navigate with caution and maintain listening watch on channels 16/72. Cancel this message on 202359 UTC Feb 22.

066/22. NORTHERN GULF. Kuwait. Charts BA 2858, 2882, 2884 and 3773. Hydrographic survey will be conducted by vessel AHTS from 15 Feb 22 in following positions:

OS-EC-A 29-24.13N 048-50.73E
 OS-EC-B 29-13.10N 048-44.42E

Mariners are advised to navigate with caution and keep listening watch on VHF channel 16.

067/22. EASTERN GULF. Dubai (Palm Deirah). Charts BA 2887, 2888, 3175 and 3176. An obstruction reported in position 25-20.90N 055-08.62E. Mariners cautioned.

068/22. SOUTHERN GULF. UAE. Charts BA 2837, 2888, 3174 and 3404. Characteristics of beacon fixed at RAK maritime city breakwater has been changed as follows:

Name : RMC Beacon.
 Colour : White.
 Characteristics: Fl. 3 Seconds.
 Height : 4 meters
 Position : 25-58.02N 056-02.83E

Mariners cautioned.

069/22. CENTRAL GULF. Bahrain. Charts BA 2837, 2847 and 2886. Cable installation operations will be conducted by vessels Atlantis, WWE-210, Mubarak, Seaworker and Donna-3 from 17 Feb 22. Cables will be laid between Ras Al Bar and Hawar Island on following route:

25-47.89N 050-34.07E
 25-46.59N 050-37.04E
 25-44.47N 050-37.68E
 25-42.04N 050-44.08E
 25-41.95N 050-45.27E

Vessels will be restricted in their ability to manoeuvre and an exclusion area of 500 meters is required to ensure the safety of the vessels and cables. Mariners are requested to navigate with caution.

070/22. IRAN. Bandar-e Pars. Charts BA 2837, 2858 and 2883. Safe water buoy in position 27-32.19N 052-28.07E permanently discontinued. Mariners cautioned.

071/22. SELF CANCELLING. Cancel Navarea IX warning 037 of 2022.

072/22. SELF CANCELLING. Cancel Navarea IX warning 377 of 2021.

073/22. SELF CANCELLING. Navigational Warnings Inforce:

2020 series: 004
 2021 series: 024, 086, 109, 152, 223, 224, 251, 292, 323, 336, 340, 364, 368, 372, 397, 398, 399, 408, 421, 445, 448, 453, 475, 477, 481, 490, 491, 492, 503 and 513.
 2022 series: 015, 020, 021, 027, 030, 033, 038, 039, 041, 052, 061, 065, 066, 067, 068, 069 and 070.

COASTAL WARNING

019/22. SELF CANCELLING. Navigational Warnings Inforce:

2020 Series: 143.
 2021 Series: 095, 096, 127 and 136.
 2022 Series: 012.

WPGs Inforced 2022: 04
 WPGs Cancelled 2022: Nil

PART – III
CORRECTIONS TO SAILING DIRECTIONS

**NP64 Red Sea and Gulf of Aden Pilot
(2021 Edition)**

**Saudi Arabia - Red Sea - Yanbu' al Baḥr —
Directions; caution**

210

After Paragraph 9.64 s line 12 Insert:

Caution. A number of STS transfer areas lie along this route, see 9.96.

Saudi Ports Authority Notice A/397/21
[NP64-No 3-Wk 07/22]

**Saudi Arabia - Yanbu' al Baḥr —
Arrival information; transhipment areas**

214

Paragraph 9.96 3-4 Replace by:

- 3 **Transhipment areas.** Extensive STS transfer areas have been established, centred on:
24°08'·00N 37°19'·00E;
23°28'·00N 37°53'·00E.

Vessels conducting STS transfer operations will be underway at slow speed and restricted in their ability to manoeuvre. Mariners should keep clear of these areas.

Saudi Ports Authority Notice A/397/21
[NP64-No 4-Wk 07/22]

PART – IV
MARINE INFORMATION

Nil

NP77, Vol D Edition 2021. Weekly Edition No. 7, Dated 17 February 2022.
 Last Updates: Weekly Edition No. 6, dated 10 February 2022.

NORTH COAST. PUERTO DE PASAIA						
D1475-1	Remove from list; deleted					
D1647 ES, I, 02570	- Puerto de Luarca. Dique del Canouco. Head	43 32-93 N 6 32-15 W	Fl(2)R 7s	19	5 Red round tower 13	<i>fl 0-5, ec 1-5, fl 0-5, ec 4-5.</i> TE 2021 *
D1834 ES, I, 04400	- Puerto de Vilanova de Arousa. Ramp. Head	42 33-77 N 8 49-93 W	Fl(2+1)G 15s	8	1 Green tower, red band 6	<i>fl 0-5, ec 1-5, fl 0-5, ec 3, fl 0-5, ec 9.</i> TE 2021 *
D7050 MG., 16 FR, L2, 37220 *	- Ampasikely	14 37-06 S 47 45-78 E	F WR	19	W 5 White metal column, R 3 on square support 8	W049°-059°(10°), R059°-071°(12°). TE 2021 *
D7360-751 *	Palm Jabel Ali. Entrance	25 02-16 N 54 59-37 E *	Fl R Red metal pole	PA *
D7360-752 *	Palm Jabel Ali. Entrance	25 02-14 N 54 59-18 E *	Fl G Green metal pole	PA *
D7722 *	- Damāgheh-ye Chābahār. Breakwater. Head	25 18-37 N 60 35-00 E *	Fl(2)G 6s	..	5 Green pile	.. *