



PAKISTAN NOTICES TO MARINERS

WEEKLY EDITION 31

Notice: 100/22

06 AUG 2022

Copies of these Notices can be obtained gratis from Mercantile Marine Department and PN Chart Depot / NAVAREA IX Headquarters, 11 Liaquat Barracks Karachi. The same can be downloaded from web: hydrography.paknavy.gov.pk.

CONTENTS

- I NOTICES TO MARINERS
- II REPRINTS OF RADIO NAVIGATIONAL WARNINGS
- III CORRECTIONS TO SAILING DIRECTIONS
- IV MARINE INFORMATION

Mariners are requested to inform the Hydrographic Department, Naval Headquarters, 11 Liaquat Barracks, Karachi, Pakistan, immediately on the discovery of new dangers, or suspected dangers to navigation and of changes or defects in aids to navigation noticed in NAVAREA IX and of shortcomings in PAK charts or publications.

Tel : + 92-21-48506151
+ 92-21-48506152
Fax : + 92-21-99201623
+ 92-21-35867737

E-mail : hydropk@paknavy.gov.pk
hydrpk@gmail.com

Web : hydrography.paknavy.gov.pk.

MUHAMMAD WASIM
Captain Pakistan Navy
Hydrographer

Hydrographic Department, Naval Headquarters, 11 Liaquat Barracks, Karachi 75530, PAKISTAN

PART – I
NOTICES TO MARINERS

100*/22 SAUDI ARABIA - Red Sea Coast - Depths.

BA Chart 2577 (INT 7151) [*previous update New Edition 13/06/2019*] WGS84 DATUM

Insert	depth, 16 ₂	(a) 21° 29′.073N., 39° 09′.152E.
Delete	depth, 15, and associated 20m contour, close S of:	(a) above

Source: Admiralty Notice to Mariners No. 3184*/2022.

PART – II
RADIO NAVIGATIONAL WARNINGS

287/22. CENTRAL GULF. Qatar. Charts BA 2523, 2837 and 2886. QMS Subhiya rig will be moved on 31 Jul 22 with support vessel Lanpan 31 from its current position 26-40.47N 052-00.58E to 25-53.70N 051-38.50E. Mariners are requested to navigate with caution and give wide berth. Cancel this message 062359 Aug 2022.

288/22. CENTRAL GULF. Qatar. Charts BA 2837, 2886 and 2887. Rig Emerald Driller will be moved on 01 Aug 22 by Halul-62, Lanpan-35 and Halul-26 from 25-52.06N, 052-46.70E to 26-00.81N 052-41.69E. Wide berth requested. Cancel this message on 052359 UTC Aug 2022.

289/22. SOUTHERN GULF. UAE. Charts BA 3175,3176 and 3405. Ajman fairway buoy reported unlit in Position 25 27.44N 055 26.56E. Mariners cautioned.

290/22. SOUTHERN GULF. UAE. Charts BA 2443, 2837, 3177 and 2889. Seismic survey in progress till 07 Aug 22 in following areas:

Receiver Boundary
 24-56.24N 053-48.04E
 24-56.15N 053-52.79E
 24-45.97N 053-53.69E
 24-45.95N 053-53.32E
 24-51.03N 053-53.47E
 24-51.16N 053-47.92E

Source Boundary
 25-00.63N 053-48.04E
 25-00.54N 053-52.65E
 24-42.72N 053-53.65E
 24-42.72N 053-53.34E
 24-46.71N 053-53.46E
 24-46.72N 053-47.79E

Fishing, anchoring and diving operations are strictly prohibited. Mariners are advised to navigate with caution and maintain listening watch on channel 16/72. Cancel this message on 072359 UTC Aug 22.

291/22. SELF CANCELLING. Reef buoy No. 1 replaced in position. Cancel Navarea IX warning 283 of 2022.

292/22. SELF CANCELLING. Well Head Tower established. Cancel Navarea IX warning 273 of 2022.

293/22. SELF CANCELLING. Buoy Relaid. Cancel Navarea IX warning 289 of 2022.

294/22. IRAN. Reshadat Oil Field. Charts BA 2886, 2887 and 2889. Sadra Sadaf-132 accommodation barge temporarily moored with anchors and marked by buoys in position 25-53.70N 052-54.80E. Wide berth requested.

295/22. IRAN. Shatt Al Arab. Charts BA 1235 and 3842. 03 lightbuoys established:

- | | | | |
|----|----------------------|----------------|----------------------|
| a. | Starboard Hand No.03 | Fl(2) 18Sec 5m | 29-50.72N 048-45.58E |
| b. | Starboard Hand No.11 | Fl(2) 18Sec 5m | 29-52.74N 048-40.94E |
| c. | Starboard Hand No.13 | Fl(2) 20Sec 5m | 29-53.64N 048-39.98E |

Mariners cautioned.

296/22. IRAN. Bushehr (Bandar-e Rostami). Charts BA 2847, 2883 and 2884. Fish farm established in area bounded by following coordinates:

- | | |
|----|----------------------|
| a. | 28-32.56N 050-54.67E |
| b. | 28-32.56N 050-54.83E |
| c. | 28-32.34N 050-54.83E |
| d. | 28-32.34N 050-54.67E |

Wide berth requested.

297/22. **NORTHERN GULF.** Kuwait. Charts 2884 and 3773. Rock removal work in progress by vessel Toalar 1003 in position 28-51.73N 048-21.53E. Mariners cautioned. Cancel this message on 12 Aug 22.

298/22 **SELF CANCELLING.** Navigational Warnings Inforce:

2021 series: 024, 086, 109, 223, 224, 292, 336, 368, 397, 398, 399, 408, 445, 448, 490 and 491.
 2022 series: 021, 027, 039, 067, 069, 080, 095, 101, 102, 112, 142, 144, 170, 172, 180, 185, 193, 194, 198, 207, 211, 218, 220, 226, 227, 231, 243, 246, 248, 257, 264, 275, 279, 280, 281, 284, 287, 290, 294, 295, 296 and 297.

COASTAL WARNING

074/22. **SELF CANCELLING.** Navigational Warnings Inforce:

2020 Series: 143.
 2021 Series: 095 and 136.
 2022 Series: 024, 027, 053, 054, 060, 063, 065 and 072.

WPGs Inforced 2022: 22
 WPGs Cancelled 2022: Nil

PART – III

CORRECTIONS TO SAILING DIRECTIONS

NP63 Persian Gulf Pilot (2021 Edition)

**United Arab Emirates - Umm al Qaywayn —
 Directions; wreck**

146

Paragraph 7.50 2 lines 1-2 *Replace by:*

- 2 **Entry.** From the outer anchorage the track leads SSE, passing:
 WSW of a dangerous wreck (25°41'·50N 55°34'·90E), thence:

Corr. Umm al Qaywayn Harbour Master
[NP63-No 70-Wk 31/22]

PART – IV

MARINE INFORMATION

NP77, Vol D Edition 2022. Weekly Edition No. 31, Dated 04 August 2022.
Last Updates: Weekly Edition No. 29, dated 21 July 2022.

D1530-2 ES, I, 00780-1 *	- Espigón de Portugalete. Jetty. Head *	43 19-82 N 3 01-55 W *	Fl Y 4s *	6 *	1 Yellow post 5 *	<i>fl 0-3</i> *
D1531-5 ES, I, 00795-7 *	- Ría. Muelle Viejo de Portugalete. Ángulo NW *	43 19-18 N 3 00-88 W *	Fl(4)G 12s *	6 *	1 Green post 5 *	<i>(fl 0-3, ec 1-7) x 3, fl 0-3, ec 5-7</i> *
D1534-15 ES, I, 00883 *	- Ria. Ribera de Zorrozaurre 1. Embarcadero *	43 16-64 N 2 58-11 W *	Q(2)R 6s *	3 *	1 Red post 4 *	<i>..</i> *
D1534-21 ES, I, 00912 *	- Ria. Ribera de Deusto 1. Embarcadero *	43 15-93 N 2 57-47 W *	Fl(4)R 12s *	7 *	1 Red post 5 *	<i>(fl 0-3, ec 1-7) x 3, fl 0-3, ec 5-7</i> *
D1634-5 ES, I, 02402	- Entrance. Ldg Lts 206-2°. Front	43 34-05 N 6 04-72 W	Q W	7	1 White round tower, red bands 3	TE 2022 *

NP77, Vol D Edition 2022. Weekly Edition No. 31, Dated 04 August 2022.
 Last Updates: Weekly Edition No. 29, dated 21 July 2022.

D2591 FR, L2, 17100 *	JORF LASFAR - Digue Principale. Head	33 07-41 N 8 38-67 W *	Fl(2)R 6s *	19 *	8 Tower 10 *	..	*
D2591-2 FR, L2, 17120 *	- Digue Principale. Spur	33 07-58 N 8 38-49 W *	Iso R 4s *	16 *	6 Tower 10 *	..	*
D2591-4 FR, L2, 17160 *	- Contre-Digue. Head	33 07-51 N 8 38-23 W *	Iso G 4s *	14 *	8 Beacon 10 *	..	*
D2815-9 ES, I, 12565	- Puerto de Arguineguin. Breakwater. Head	27 45-51 N 15 41-19 W	Fl G 5s	12	5 Green tower with white conical base 5 * *	<i>fl 0-5</i>	
D2815-92 ES, I, 12570	- Puerto de Arguineguin. Outer Breakwater. Head	27 45-46 N 15 41-09 W	Fl R 5s	7	3 Red and white tower 5 *	<i>fl 0-5</i>	*
D6576	PORTO DE PEBANE Remove from list; deleted						
D7653-6 *	- No 25	30 12-19 N 48 57-85 E *	Fl G 6s *	.. *	7 Green beacon * *	..	*
D7655-5 *	- No 29	30 20-81 N 48 53-64 E *	Fl(3)G 9s *	.. *	7 Green beacon * *	..	*
D7655-6 *	- No 40	30 22-82 N 48 54-28 E *	Fl R 3s *	.. *	7 Red beacon * *	..	*
D7655-8 *	- No 31	30 23-99 N 48 55-77 E *	Fl G 3s *	.. *	7 Green beacon * *	..	*
D7655-9 *	- No 42	30 24-55 N 48 55-73 E *	Fl R 3s *	.. *	7 Red beacon * *	..	*